



Notification of Hazardous Waste Site

CONFIDENTIAL

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

#4 810609 - IHS-000-001-004

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Indiana Steel & Wire, Division of General Cable
Street 2000 E. Jackson Street
City Muncie State IN Zip Code 47302

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site same as A
Street 2000 E. Jackson Street
City Muncie County Delaware State IN Zip Code 47302

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Clark, Gregory, Plant Environmental Engineer
Phone 317-288-3601

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1952 To (Year) 1980

EPA Region 5 Records Ctr.



303732

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☒ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☒ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☒ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

F008
D008

000323 JUN -9 81

JUN 12 1981

Notification of Hazardous Waste Site

Side Two

CONFIDENTIAL

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 17,500 C

gallons _____

Total Facility Area

square feet _____

acres 1 A

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Site is located behind (north) our plant.
See attached map.

Contiguous

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Sludges from several plating operations were routinely dumped at the site for a number of years. The sludges were covered once a year with dirt. The landfill is presently closed and has been covered with two feet of dirt.


Following analysis of test soil borings, discussions were initiated with the Indiana State Board of Health regarding the contents of this site. In addition, monitoring wells have been installed around the site, for the purpose of on-going analysis of ground water.

J Signature and Title:


The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name James Curtis
Street 2000 E. Jackson Street
City Muncie State IN Zip Code 47302
Signature James E. Curtis Date 5/11/81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other



CONFIDENTIAL



Area Career Center

Longfellow

Central High School

Penn Central R.R.

Penn Central R.R.

Franklin J.H.S.

Middletown Gardens Victor Ct.

Imperial Lane

Esther Lane

Lebanon



500 West Putnam Avenue, Greenwich, Connecticut 06830 (203) 661-0100
Cable Address: GK TECHNOLOGIES GREENWICH CONNECTICUT Telex Number 996439


June 9, 1981

US EPA Region 5
Sites Notification
Chicago, Illinois 60604

Dear Sirs:

Enclosed are five notifications on EPA Form 8900 submitted as required by Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980.

Very truly yours,


J. F. Kent, Jr.

JFK:mlh
Enc.


JUN 12 1981

A Division of
GK Technologies
Incorporated

chnologies

rated

Avenue, Greenwich, Connecticut 06830



GK Technologies

Incorporated

500 WEST PUTNAM AVENUE, GREENWICH, CONNECTICUT 06830

US EPA REGION 5
SITES NOTIFICATION
CHICAGO, ILLINOIS 60604

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

POSTMASTER: RETURN POSTAGE GUARANTEED

ML-1

TIFIED

410231

MAIL

**RETURN RECEIPT
REQUESTED**

CALL NUMB

DATE:

400

6-9-80

SKS red
6-2480

U.S. ENVIRONMENTAL PROTECTION AGENCY

REGION V

HAZARDOUS MATERIAL ENFORCEMENT AND RESPONSE PROGRAM

Ind. Steel and Wire Co.

SITE NAME:

2000 East Jackson, Muncie, Ind.

SITE ADDRESS:

Has learned from two employees (6/9/80 call)

HOW IDENTIFIED:

that the company is burying scienide in the grounds

SITE DESCRIPTION:

behind the company; they buried at least 300 cans

at once; the site is near White River; supervisors

have been instructed to remove the label from

WASTE RELATED INFO:

each can; the company has no permit for this. A

bulldozer operator ruptured at least one can.

HAZARD IDENTIFICATION:

Patricia Bilbrey

NAME OF CALLER:

2300 East 8th St., Muncie 47302

ADDRESS OF CALLER:

217 282-5648 or 289-1861; would like someone to call 8-336-7000

TELEPHONE NUMBER:

Has this been reported to any state or local authority? How? When?

FOLLOW UP

Call is get additional information then HMERP

This could contaminate drinking water.